

Oil Field Environmental Incident Summary

Incident: 20160809191317 **Date/Time of Notice:** 08/09/2016 19:13

Responsible Party: PETRO-HUNT, L.L.C.

Well Operator: PETRO-HUNT, L.L.C.

Well Name: RAY O. HANSON 1

Field Name: NORTH TIOGA

Well File #: 2495

Date Incident: 8/9/2016

Time Incident: 08:00

Facility ID Number:

County: WILLIAMS

Twp: 159

Rng: 95

Sec: 1

Qtr:

Location Description:

Submitted By: Shawn Reisenauer

Received By:

Contact Person: Shawn Reisenauer
PO BOX 935
BISMARCK, ND 58502

General Land Use: Well/Facility Site

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Stuffing Box Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	3	Barrels	2	Barrels		
Brine	2	Barrels	1	Barrels		
Other					3	barrels

Description of Other Released Contaminant:

Inspected:

Written Report Received: 8/18/2016

Clean Up Concluded: 8/10/2016

Risk Evaluation:

None

Areal Extent:

25'x50'

Potential Environmental Impacts:

Topsoil

Action Taken or Planned:

Fluid on location was recovered. Waiting to talk with surface owner on cropland.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 8/10/2016 ***Status:*** Reviewed - Follow-up Required

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release impacted areas off location. Follow-up is required.

Date: 8/22/2016 ***Status:*** Inspection

Author: Nieraeth, Shawna

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Uncovered dirt pile on SE side of well pad. Looks as if a small section of field behind the dirt pile has been excavated. Coordinates 48.631524 -102.888455